

VEHICLE INSPECTION REPORT

SA71KJV

Fiat Doblo II 1.6 MULTIJET 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/11/2021

Year 2021

Mileage 66,676 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V27439

Body Style Dropside

MOT Due 05/02/2026

CAP Clean £7,125.00

CAP Average £6,500.00

CAP Below £5,450.00

Gearbox MANUAL

Gears 5

AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Wing nsf
Dented
Over 30mm



6: Wing nsf
Dented
Over 30mm



7: Door nsf
Dented
With Paint Damage



8: Lamp nsr
Broken
Replace



9: Tailgate
Dented
With Paint Damage



10: Door osf
Scratched
Over 25mm Thru Paint



11: Wing osf
Dented
With Paint Damage



12: Door Pad osf
Soiled
Heavy



13: Seat Back Cover osf
Torn
Over 3mm



14: Seat Base Cover osf
Soiled
Heavy



15: Seat Back Cover nsf
Soiled
Heavy



16: Seat Base Cover nsf
Soiled
Heavy



17: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	Yes
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		