

VEHICLE INSPECTION REPORT

PJ71NLK

Fiat Doblo II 1.6 MULTIJET 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/12/2021

Year 2021

Mileage 72,861 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V67371

Body Style Dropside L2

MOT Due 11/11/2025

CAP Clean £6,850.00

CAP Average £6,250.00

CAP Below £5,225.00

Gearbox MANUAL

Gears 5

WARNING LIGHT ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Dented
Over 30mm



6: Panel Rear
Missing
Replace



7: Door osf
Dented
With Paint Damage



8: Door osf
Scratched
Over 25mm Thru Paint



9: Carpets Front
Holed
Over 3mm



10: Fascia Panel
Missing
Replace



11: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		