

VEHICLE INSPECTION REPORT

BL68OVH

Iveco Eurocargo 180-250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/02/2019

Year 2019

Mileage 293,088 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFA71TJ002688735

Body Style Curtainside

Service history Yes

Service documents Electronic / Online

MOT Due 31/05/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

Rear Doors Barn

WARNING LIGHT ON DASH

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

NSI3

OSI3

NSO3

OSO3

NSI4

OSI4

NSO4

OSO4

Features

- Bluetooth connection
- Digital radio
- Drivers airbag
- Cruise control
- Radio/CD
- Central locking
- Front parking sensor
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Missing
Replace



3: Door nsr
Scratched
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint




5: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



6: Carpets Front
Torn
Over 10mm



7: Dash Warning Lights
Displayed
No Action



8: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		