

VEHICLE INSPECTION REPORT

CX18SWZ

Fiat Doblo 1.6 MULTIJET 16V SX

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 24/05/2018

Year 2018

Mileage 65,335 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006J65598

Body Style Panel Van L2

MOT Due 15/05/2026

CAP Clean £3,900.00

CAP Average £3,375.00

CAP Below £2,650.00

Gearbox MANUAL

Gears 5

TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Digital radio
- Drivers airbag
- Radio/CD
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel nsr
Dented
With Paint Damage



4: Fuel Flap
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel osr
Dented
Over 30mm



7: Qtr Panel osr
Dented
With Paint Damage



8: Door osf
Dented
Over 30mm



9: Fascia Panel
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		