

## **VEHICLE INSPECTION REPORT**

FP68AVD

### Vauxhall Vivaro 2700 1.6 CDTI 95PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow		
Details					
Reg. date	30/10/2018	VIN	W0VF7F607KV613292	<b>CAP Below</b>	£4,075.00
Year	2018	Body Style	Panel Van L1	Gearbox	MANUAL
Mileage	47,899 Miles Warranted	MOT Due	Expired	Gears	6
		CAP Clean	£6,000.00		
Fuel Type	Diesel	CAP Average	£5,200.00		
Colour	WHITE				

\*WARNING LIGHTS ON DASH, POWER STEERING ISSUES, ONLY RUNS WITH JUMP PACK ATTACHED\* SIDE LOADING DOOR, E/MIRRORS

Tyres NSF

NSR OSF

OSR

**Spare** 

### **Features**

Front electric windows

#### **Photos**

















# **Condition Check**



## **Damage Photos**



1: Other N/A N/A



2: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



3: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



4: Bonnet Chipped Multiple Chips



5: Other N/A N/A



6: Door nsf Dented With Paint Damage



7: Door nsf Scratched Over 25mm Thru Paint



8: Door nsf Scratched UpTo 25mm Thru Paint



9: Door nsr Dented Between 10mm + 30mm



10: Door nsr Scratched Over 25mm Thru Paint



11: Other N/A N/A



12: Other N/A N/A



13: Door osr Dented Over 2 UpTo 10mm



14: Door osr Dented Over 2 UpTo 10mm



15: Door osr Dented Between 10mm + 30mm



16: Bumper Rear Moulding Scuffed (Unpainted) UpTo 100mm



17: Qtr Panel osr Scratched Over 25mm Thru Paint



18: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



19: Other N/A N/A

### Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Parking Brake		OK	Gearbox Static Gear Sel	ection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	ıminated	Fault