

VEHICLE INSPECTION REPORT

BJ18VZH

Nissan NV300 1.6 DCI 120PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 31/03/2018

Year 2018

Mileage 88,880 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VNVF4000457327847

Body Style Panel Van L2

MOT Due 30/03/2026

CAP Clean £5,350.00

CAP Average £4,575.00

CAP Below £3,575.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH NO ACCESS TO SIDE DOOR, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Grille Front
Broken
Replace



2: Grille Front
Broken
Replace



3: Bonnet
Dented
With Paint Damage



4: Bonnet
Scratched
Over 25mm Not Thru Paint



5: Other
N/A
N/A



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Door Mirror Assy nsf
Broken
Replace



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Dented
Between 10mm + 30mm



12: Door nsr
Dented
2 Or Less UpTo 10mm



13: Door osr
Dented
Between 10mm + 30mm



14: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint



15: Door Mirror Assy osf
Broken
Replace

16: B Post os
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	Fault		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK