

VEHICLE INSPECTION REPORT

WX17KFU

Isuzu D-Max 2.5TD

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	20/05/2017	VIN	MPATFS86JFT031375	CAP Below	£4,325.00
Year	2017	Body Style	Pickup Double Cab	Gearbox	MANUAL
Mileage	71,092 Miles Warranted	MOT Due	16/04/2026	Gears	6
		CAP Clean	£6,725.00	Axle Combi	4x4
Fuel Type	Diesel	CAP Average	£5,700.00	-	
Colour	WHITE		i		
TOW BAR, ROC Tyres NSF	OF RACK				
NSR					
OSF					
OSR					
Spare					

Features

- Bluetooth connection
- Front electric windowsCloth seat trim
- · Park assist camera
- · Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos













Commercial Vehicle Auctions Limited












Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint



3: Qtr Panel nsr Cracked Replace



4: Qtr Panel osr Scratched Over 25mm Thru Paint



5: Qtr Panel osr Chipped Multiple Chips



6: Wing osf Dented Over 30mm



7: Bumper Front Scratched Over 100mm Thru Paint



8: Seat Base Cover nsf Soiled Heavy



9: Fascia Panel Soiled Heavy

Interior

Carpet Condition Seat Condition	OK Poor		Jpholstery Condition Odour	Poor No	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			