

VEHICLE INSPECTION REPORT

WX66HZD

Isuzu D-Max 2.5TD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/02/2017

Year 2017

Mileage 72,285 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN MPATFS86JFT031356

Body Style Pickup Double Cab

MOT Due 31/01/2026

CAP Clean £6,425.00

CAP Average £5,450.00

CAP Below £4,125.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

TOW BAR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Radio/CD
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bonnet
Dented
With Paint Damage



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Number Plate Front
Broken
Replace



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Wing nsf
Dented
With Paint Damage



7: Wing nsf
Dented
Over 30mm



8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Door nsf
Dented
Over 30mm



10: Door nsf
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
Over 30mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Qtr Panel nsr
Dented
With Paint Damage



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage




17: Sill os
Dented
With Paint Damage



18: Qtr Panel osr
Dented
Over 30% Of Panel



19: Door osf
Dented
With Paint Damage



20: Door osf
Dented
With Paint Damage



21: Wing osf
Dented
Over 30% Of Panel



22: Bumper Front
Hole
Over 25mm



23: Seat Base Cover osf
Holed
Over 3mm



24: Fascia Panel
Soiled
Heavy



25: Seat Base Cover nsf
Soiled
Heavy



26: Fascia Panel
Scuffed
Over 25mm



27: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		