

VEHICLE INSPECTION REPORT

BX59DFY

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	17/11/2009	VIN	XLRAE45FF0L354076	Axle Combi	4x2
Year	2009	Body Style	MOBILE WORKSHOP	Rear Suspension	Steel
Mileage	202,533 Km Warranted	MOT Due	31/01/2026	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	MANUAL		

GARDNER DENVER HYDRAPAK, KITCHENETTE C/W GAS HOB & SINK


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Door osf
Chipped
Multiple Chips



6: Door Pad osf
Soiled
Heavy



7: Seat Base Cover osf
Holed
Over 3mm



8: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		