

VEHICLE INSPECTION REPORT

FP69ZCK

Vauxhall Vivaro 2900 1.5D 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/12/2019

Year 2019

Mileage 52,685 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VXEVBYHRKL7009173

Body Style Panel Van L1

MOT Due 26/09/2026

CAP Clean £8,150.00

CAP Average £7,150.00

CAP Below £5,725.00

Gearbox MANUAL

Gears 6

SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos






Condition Check



Damage Photos



1: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Door nsr
Scratched
Over 25mm Not Thru Paint

4: Door nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Dented
Over 30mm



9: Qtr Panel osr
Dented
With Paint Damage

10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Door osf
Dented
With Paint Damage

12: Door osf
Dented
Over 2 UpTo 10mm



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	