

VEHICLE INSPECTION REPORT

PO70ZFY

Mitsubishi L200 DI-D 2.3 Barbarian X 150PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	01/09/2020	VIN	MMCJLKL60LH018800	CAP Below	£12,700.00
Year	2020	Body Style	Pickup Double Cab	Gearbox	AUTOMATIC
Mileage	57,267 Miles Not Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£17,350.00	Axle Combi	4x4
Colour	BLUE	CAP Average	£15,450.00		

CRACK IN WINDSCREEN, WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, E/ MORRORS, HEATED SEATS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Park assist camera
- Air conditioning
- Drivers airbag
- Cruise control
- Rear parking sensor
- Front electric windows
- Passenger airbag
- Front parking sensor
- Auxiliary input socket
- Rear electric windows
- Central locking
- Heated front seat
- Digital radio
- Metallic Paint
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Roof
Dented
With Paint Damage



2: Screen Front
Cracked
Replace



3: Roof
Dented
Over 30mm



4: Bonnet
Poor Previous Repair
Poor Colour



5: Roof
Dented
With Paint Damage



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Chipped
Multiple Chips



8: Bumper Rear Moulding
Broken
Replace



9: Tailgate
 Scratched
 Over 25mm Thru Paint



10: Lamp osr
 Broken
 Replace



11: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



12: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



13: Door osr
 Chipped
 Multiple Chips



14: Door osf
 Chipped
 Multiple Chips



15: Wing osf
Dented
With Paint Damage



16: Seat Back Cover osr
Soiled
Heavy



17: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault