

VEHICLE INSPECTION REPORT

KV71XJZ

Mercedes-Benz Sprinter 315

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 17/09/2021

Year 2021

Mileage 85,292 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P370958

Body Style Panel Van L3

MOT Due 07/07/2026

CAP Clean £14,050.00

CAP Average £12,750.00

CAP Below £10,700.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, TOW BAR, AD-BLUE

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Rear parking sensor
- Passenger airbag

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Dented
Over 30mm



3: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Bumper Rear Moulding
Broken
Replace



6: Door nsr
Dented
Over 30mm



7: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		