

VEHICLE INSPECTION REPORT

NK17UFB

Scania P 250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	14/03/2017	Body Style	Fridge Box	Axle Combi	4x2
Year	2017	Service history	Yes	Rear Suspension	Air
Mileage	653,961 Km Warranted	Service documents	Printout	Rear Doors	Roller
Fuel Type	Diesel	MOT Due	31/10/2026	Tail Lift	Column
Colour	WHITE	Cab Type	DAY CAB		
VIN	YS2P4X20002121208	Gearbox	AUTOMATIC		

THERMOKING T1000R UNIT


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Radio/CD
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Cracked
Replace



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy osf
Broken
Replace



8: Panel Front
Cracked
Replace



9: Door osf
Scratched
Over 25mm Thru Paint



10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			