

VEHICLE INSPECTION REPORT

SJ19NZZ

Volvo FMX 420

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/03/2019

Year 2019

Mileage 347,697 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YV2XTW0G9KA839430

Body Style Tipper

MOT Due 31/10/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

WARNING LIGHT ON DASH THOMPSONS BODY, HYVA TIPPING GEAR, SHEETING SYSTEM, SURROUND CAMERA SYSTEM

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint



2: Other
N/A
N/A



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



4: Door nsf
Dented
Between 10mm + 30mm



5: Other
N/A
N/A



6: Other
N/A
N/A



7: Other
N/A
N/A



8: Door osf
Scratched
UpTo 25mm Thru Paint



9: Door osf
 Scratched
 UpTo 25mm Thru Paint



10: Seat Base Cover osf
 Torn
 Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK