

VEHICLE INSPECTION REPORT

PE15HJC

Daf LF 150

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow		
Details					
Reg. date	01/04/2015	Body Style	Box Van	Axle Combi	4x2
Year	2015	Service history	Yes	Rear Suspension	Steel
Mileage	474,444 Km Warranted	Service documents	Printout	Rear Doors	Roller
Fuel Type	Diesel	MOT Due	31/01/2026	Tail Lift	Tuckaway
Colour	RED	Cab Type	DAY CAB		
VIN	XLRAEL1500L442667	Gearbox	MANUAL		

COLLECTED AS NON-RUNNER, MECH W/O - CAB CORROSION/TAIL LIFT PLATFORM SINGLE O/S ROLLER DOOR

Tyres


NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OS03	OSO4	

Features

· Park assist camera

Radio/CD

Condition Check



Damage Photos



1: Door osf Chipped Edge Chip



2: Door osf Scratched Over 25mm Thru Paint



3: Bonnet Chipped Multiple Chips



4: Bonnet Dented With Paint Damage



5: Door nsf Chipped Multiple Chips



6: B Post ns Rusted Over 5mm



7: Qtr Panel nsr Chipped Multiple Chips



8: Qtr Panel osr Chipped Multiple Chips

Interior

Carpet Condition - Seat Condition -		Jpholstery Condition - Odour -	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK

OK

Steering

OK

Windows