

VEHICLE INSPECTION REPORT

YR69FZO

Ford Ranger XL 2.0 EcoBlue 170PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	17/09/2019	VIN	6FPPXXMJ2PKY19247	CAP Below	£5,875.00
Year	2019	Body Style	Pickup Double Cab	Gearbox	MANUAL
Mileage	113,777 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£8,350.00	Doors	4
Colour	WHITE	CAP Average	£7,325.00	Axle Combi	4x4

WARNING LIGHT ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/Cassette
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing osf
Dented
Over 30mm

4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Tailgate
Dented
With Paint Damage

6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage

8: Door nsf
Dented
Over 30mm



9: Roof
 Rusted
 Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	Fault	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Roof / sunroof	OK		Radio	OK	
Windows	OK		Steering	OK	