

VEHICLE INSPECTION REPORT

2625586

Iveco Eurocargo 110E21

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	25/08/2014	VIN	ZCFAF1EF802625586	Axle Combi	4x2
Year	2014	Body Style	Curtainside	Rear Suspension	Steel
Mileage	42,667 Km Warranted	MOT Due	30/11/2025	Rear Doors	Barn
Fuel Type	DIESEL	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

MOD 654 FORM T/F

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Number Plate Front
Missing
Replace



3: Screen Front
Chipped
Over 10mm



4: Door Mirror Assy nsf
Missing
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Other
N/A
N/A



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Door Mirror Assy osf
 Scuffed (Unpainted)
 UpTo 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK