

VEHICLE INSPECTION REPORT

2625577

Iveco Eurocargo 180E25

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	25/08/2014	VIN	ZCFA61TJ802625577	Axle Combi	4x2
Year	2014	Body Style	Box Van	Rear Suspension	Steel
Mileage	216,155 Km Warranted	MOT Due	31/12/2025	Tail Lift	Column
Fuel Type	DIESEL	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

MOD 654 FORM IN OFFICE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Fog Lamp Surround os
Broken
Replace



3: Bumper Front Moulding
Broken
Replace



4: Other
N/A
N/A



5: Screen Front
Chipped
UpTo 10mm



6: Number Plate Front
Missing
Replace



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Door Mirror Assy nsf
Missing
Replace



9: Other
N/A
N/A



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Door Mirror Assy osf
Broken
Replace



12: Other
N/A
N/A



13: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK