

VEHICLE INSPECTION REPORT

SF21ULN

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 17/05/2021

Year 2021

Mileage 78,048 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006T88574

Body Style Dropside L2

MOT Due 16/05/2026

CAP Clean £6,225.00

CAP Average £5,650.00

CAP Below £4,750.00

Gearbox MANUAL

Gears 5

EXCESSIVELY SMOKING AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front Moulding
Missing
Replace



3: Bumper Front
Cracked
Over 25mm



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Dented
With Paint Damage



6: B Post ns
Dented
Over 30mm



7: Qtr Panel nsr
Dented
With Paint Damage



8: Lamp osr
Broken
Replace



9: Bumper Rear
Dented
Over 30mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: B Post os
Dented
Over 30mm



13: Door Mirror Assy osf
Broken
Replace



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door osf
Dented
With Paint Damage



16: Wing osf
Dented
Over 30mm



17: Door osf
Dented
With Paint Damage



18: Fascia Panel
Missing
Replace



19: Fascia Panel
Missing
Replace



20: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	Fault
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		