

VEHICLE INSPECTION REPORT

PN71BVS

Fiat Doblo Work Up 1.6 Multijet II

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	02/12/2021	VIN	ZFA26300006V35899	CAP Below	£4,875.00
Year	2021	Body Style	Pick-up	Gearbox	MANUAL
Mileage	79,381 Miles Warranted	MOT Due	01/12/2025	Gears	5
Fuel Type	Diesel	CAP Clean	£6,350.00		
Colour	WHITE	CAP Average	£5,800.00		

WARNING LIGHTS ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Roof
Dented
Over 30mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Bumper Front
Insecure
Action Required



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Qtr Panel Trim ns
Broken
Replace



8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: B Post os
Dented
With Paint Damage



11: Door osf
Dented
With Paint Damage



12: Wing osf
Dented
Over 30% Of Panel



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover osf
Holed
Over 3mm



16: Seat Back Cover osf
Holed
Over 3mm



17: Fascia Panel
Missing
Replace



18: Fascia Panel
Soiled
Heavy



19: Seat Base Cover nsf
Soiled
Heavy



20: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		