

VEHICLE INSPECTION REPORT

SV16KUD

Mercedes-Benz Actros 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present


Details


Reg. date	31/07/2016	VIN	WDB96300320056102	Axle Combi	4x2
Year	2016	Body Style	Curtainside	Rear Suspension	Air
Mileage	503,589 Km Warranted	MOT Due	30/11/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	CLASSICSPACE CAB	Tail Lift	Tuckaway
Colour	WHITE	Gearbox	AUTOMATIC		

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



2: Other
N/A
N/A

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK