

VEHICLE INSPECTION REPORT

SK12XNV

Volkswagen Crafter CR35 2.0 TDI 109PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	29/03/2012	Keys	2	Cab Type	DAY CAB
Year	2012	Service history	Full	Gearbox	MANUAL
Mileage	94,702 Miles Warranted	Service documents	Printout	Gears	6
Fuel Type	Diesel	MOT Due	04/04/2026	Doors	4
Colour	WHITE	CAP Clean	£2,900.00	Axle Combi	4x2
VIN	WV1ZZZ2FZC7007684	CAP Average	£2,300.00	Steering Combi	Standard Axle
Body Style	Dropside LWB	CAP Below	£1,525.00	Rear Suspension	Steel

WARNING LIGHTS ON DASH, IN LIMP MODE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Cloth seat trim
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Seat Base Cover nsf
Torn
Over 3mm



3: Bonnet
Dented
Over 30mm



4: Wing osf
Rusted
Over 5mm



5: Door osf
Dented
Over 2 UpTo 10mm



6: Qtr Panel osr
Dented
With Paint Damage



7: Tailgate
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Over 30mm



9: Door nsr
Dented
With Paint Damage



10: Sill ns
Rusted
Over 5mm



11: Wing nsf
Rusted
Over 5mm

Interior

Carpet Condition	Average		Upholstery Condition	-
Seat Condition	Poor		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	Fault		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows	OK	Radio	OK
		Steering	OK