

VEHICLE INSPECTION REPORT

BJ16UJU

Ford Transit 350 TREND 2.2 TDCi 125ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/05/2016

Year 2016

Mileage 138,013 Miles
Warranted

Fuel Type Diesel

Colour SILVER

VIN WF0XXXTTGXGA17559

Body Style Panel Van L3

MOT Due 08/12/2025

CAP Clean £3,575.00

CAP Average £2,950.00

CAP Below £2,175.00

Gearbox MANUAL

Gears 6

DRIVER SIDE WINDOW MISSING SIDE LOADING DOOR

Tyres

NSF

NSR

OSF


OSR




Spare

Features


- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
1 To 5

2: Moulding of Wing
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Dented
Over 2 UpTo 10mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm

6: Door Moulding nsf
Broken
Replace



7: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

8: Other
N/A
N/A



9: Door nsr
Dented
Over 30mm

10: Door nsr
Dented
Between 10mm + 30mm



11: Door nsr
Scratched
Over 25mm Thru Paint

12: Door nsr
Dented
Between 10mm + 30mm



13: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm

14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

16: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel nsr
Dented
With Paint Damage

18: Door nsr
Dented
With Paint Damage



19: Door nsr
Dented
With Paint Damage

20: Door nsr
Hole
Over 10mm



21: Door nsr
Dented
Over 30mm



22: Door osr
Dented
Over 30mm



23: Door osr
Scratched
Over 25mm Thru Paint



24: Door osr
Scratched
UpTo 25mm Thru Paint




25: Door osr
Dented
With Paint Damage



26: Door osr
Dented
With Paint Damage





27: Bumper Rear Moulding
Broken
Replace

28: Qtr Panel osr
Dented
Over 30mm



29: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

30: Qtr Panel osr
Dented
With Paint Damage



31: Qtr Panel osr
Dented
With Paint Damage

32: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



33: Door Window osf
Missing
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK