

VEHICLE INSPECTION REPORT

BK14ANU

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	10/03/2014	VIN	ZCFA675B402623060	Cab Type	DAY CAB
Year	2014	Body Style	Box Van	Gearbox	MANUAL
Mileage	775,834 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	28/02/2026	Tail Lift	Cantilever

COLLECTED AS NON-RUNNER, TURBO/EXHAUST ISSUES

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

8: Door osf
Scratched
Over 25mm Thru Paint



9: Fascia Panel
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		