

VEHICLE INSPECTION REPORT

PF67KDN

Fiat Ducato 2.3 MULTI JET 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/02/2018

Year 2018

Mileage 154,997 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002F41805

Body Style Panel Van LWB

MOT Due 13/02/2026

CAP Clean £3,200.00

CAP Average £2,750.00

CAP Below £2,125.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Missing
Replace

2: Bumper Front Moulding
Missing
Replace



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Badgedecal Front
Missing
Replace



5: Grille Front
Scratched (Painted)
Over 25mm Not Thru Paint

6: Bonnet
Chipped
Multiple Chips



7: Screen Front
Chipped
UpTo 10mm

8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Door Mirror Assy nsf
Broken
Replace

10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsr
Scratched
Over 25mm Thru Paint

12: Door Moulding nsr
Missing
Replace



13: Qtr Panel Moulding ns
Missing
Replace

14: Qtr Panel nsr
Scratched
Rusted



15: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

16: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



17: Bumper Rear Moulding
Broken
Replace

18: Qtr Panel nsr
Dented
With Paint Damage



19: Door nsr
Chipped
1 To 5

20: Door nsr
Chipped
Multiple Chips



21: Door osr
Chipped
Edge Chip

22: Bumper Rear Moulding
Broken
Replace



23: Qtr Panel Moulding os
Broken
Replace

24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm

26: Qtr Panel osr
Cracked
Replace



27: Door osf
Chipped
Multiple Chips

28: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



29: Sill os
Rusted
Over 5mm

30: Wing osf
Scratched
Over 25mm Thru Paint



31: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK