

VEHICLE INSPECTION REPORT

MV19UAH

Scania P 320

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/06/2019

Colour WHITE

Cab Type SLEEPER CAB

Year 2019

VIN YS2P6X20005529261

Gearbox AUTOMATIC

Mileage 342,463 Km Warranted

Body Style Beavertail

Axle Combi 6x2

Fuel Type Diesel

MOT Due 31/05/2026

Rear Suspension Air

CHEESEWEDGE BODY, CRACKED WINDSCREEN, REAR LIFT, WINCH, WEIGH SYSTEM, REAR VIEW CAMERA.

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
1 To 5



3: Wing osf
Dented
Over 30mm

4: Door osf
Dented
Over 30mm



5: Qtr Panel osr
Rusted
Over 5mm

6: Qtr Panel nsr
Rusted
Over 5mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Wing nsf
Dented
With Paint Damage



9: Screen Front
Cracked
Replace

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK