

VEHICLE INSPECTION REPORT

BK14AOF

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/03/2014

VIN ZCFA675B802623062

Axle Combi 4x2

Year 2014

Body Style Box Van

Rear Suspension Steel

Mileage 411,467 Km Warranted

MOT Due 30/04/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

AD-BLUE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1





OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

2: Bonnet
Cracked
Replace



3: Bumper Front
Hole
Over 25mm

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Other
N/A
N/A

6: Door nsf
Rusted
Over 5mm



7: Door Moulding nsf
Scratched (Painted)
Over 25mm Not Thru Paint

8: Panel Rear
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Bumper Rear
Rusted
Over 5mm



11: Panel Rear
Scratched
Over 25mm Thru Paint

12: Other
N/A
N/A



13: Other
N/A
N/A

14: Door osf
Scratched
Over 25mm Thru Paint



15: Seat Base Cover osf
 Holed
 Over 3mm

Interior

Carpet Condition		-	Upholstery Condition		-
Seat Condition		-	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	