

# VEHICLE INSPECTION REPORT

**PE63NFN**

## Daf LF 45.140

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 11/11/2013

Year 2013

Mileage 1,012,464 Km  
Warranted

Fuel Type Diesel

Colour RED

VIN XLRAE45FF0L432423

Body Style Box Van

Service history Yes

Service documents Printout

MOT Due 31/03/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Air

Tail Lift Cantilever

\*COLLECTED AS NON-RUNNER - ENGINE KNOCKING, FUEL CAP MISSING\*

### Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

## Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Panel Front  
Cracked  
Replace



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Bonnet  
Chipped  
Multiple Chips

4: Panel Front  
Cracked  
Replace



5: Bumper Front  
Dented  
With Paint Damage

6: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

8: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel osr  
Dented  
With Paint Damage

10: Door osf  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Chipped  
Multiple Chips

12: Screen Front  
Chipped  
Over 10mm



13: Door Pad osf  
Soiled  
Heavy

14: Fascia Panel  
Holed  
Over 3mm

## Interior

|                       |    |                       |      |
|-----------------------|----|-----------------------|------|
| Carpet Condition      | OK | Upholstery Condition  | Poor |
| Seat Condition        | OK | Odour                 | -    |
| Engine Runs           | OK | No Excessive Smoking  | OK   |
| EML light illuminated | OK | DPF light illuminated | OK   |
| ABS light illuminated | OK |                       |      |