

VEHICLE INSPECTION REPORT

PJ13XEW

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	22/08/2013	VIN	XLRAE45FF0L428082	Gears	5
Year	2013	Body Style	Box Van	Doors	2
Mileage	235,402 Km Warranted	MOT Due	28/02/2026	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB	Rear Doors	Roller
Colour	ORANGE	Gearbox	Manual	Tail Lift	Tuckaway


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Sill os
Scratched
Over 25mm Thru Paint

2: Carpets Front
Holed
Over 3mm



3: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

4: Qtr Panel osr
Rusted
Over 5mm



5: Tailgate
Rusted
Over 5mm

6: Qtr Panel nsr
Dented
Over 30mm



7: Door nsf
Dented
With Paint Damage

8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

10: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		Fault
ABS light illuminated		OK	Service indicator light illuminated		OK