

VEHICLE INSPECTION REPORT

PN63DME

Daf LF 45.160

Inspection		Vehicle						
Conditions	Outdoors - Good light	VAT		Plus VAT				
Serious Damage?	No	V5		To Follow		_		
Details								
Reg. date	10/09/2013	Body Style		Box Van		Axle Combi	4x2	
Year	2013	Keys		1		Rear Suspension	Steel	
Mileage	457,593 Km Warranted	Cab Type		DAY CAB		Rear Doors	Roller	
Fuel Type	Diesel	Gearbox		Manual		Tail Lift	Tuckaway	
Colour	ORANGE	Gears		5				
VIN	XLRAE45FF0L429188	Doors		2		_		
Tyres								
NSF	NSI1	N:	SI2		NSI3		NSI4	
OSF	OSI1	OSI2			OSI3		OSI4	
Spare	NSO1	N:	NSO2		NSO3		NSO4	
-	OS01	0:	SO2	OS03			DSO4	

Features

- Cruise controlCloth seat trim
- Front electric windows
- Drivers airbag
- Central locking

Photos


















Condition Check



Damage Photos



1: Seat Base Cover osf Torn Over 3mm



2: Bonnet Chipped Multiple Chips



3: Wing osf Cracked Replace



4: Door osf Dented Over 30mm



5: Qtr Panel osr Hole Over 10mm



6: Tailgate Rusted Over 5mm



7: Qtr Panel nsr Dented Over 30mm



8: B Post ns Cracked Replace



9: Door Moulding nsf Scuffed (Unpainted) Over 100mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
EML light illuminated		OK	Oil warning light illumina	ated	OK
Airbag light illuminated		OK	DPF light illuminated		Fault
ABS light illuminated		OK	Service indicator light illu	uminated	OK