

VEHICLE INSPECTION REPORT

DK17KWZ

Man TGS 26.360

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	09/06/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMA18SZZ6HP088469	Gearbox	MANUAL
Mileage	232,419 Km Warranted	Body Style	Dropside & Crane	Axle Combi	6x2
Fuel Type	Diesel	MOT Due	31/01/2026	Rear Suspension	Air

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420K REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Fog Lamp Surround of
Scuffed (Unpainted)
Over 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Screen Front
Chipped
UpTo 10mm



5: Bonnet
Chipped
Multiple Chips

6: Fog Lamp Surround ns
Scuffed (Unpainted)
Over 100mm



7: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Other
N/A
N/A

10: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



11: Door nsf
Scratched
Over 25mm Thru Paint

12: Door Mirror Assy nsf
Broken
Replace



13: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

14: Other
N/A
N/A



15: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

16: Door osf
Scratched
Over 25mm Thru Paint



17: Door osf
Chipped
Edge Chip

18: Other
N/A
N/A



19: Door Pad osf
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK