

VEHICLE INSPECTION REPORT

PK71JFO

Fiat Ducato 2.3

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 26/10/2021

Year 2021

Mileage 111,435 Miles
Warranted

Fuel Type Diesel

Colour MULTI-COLOURED

VIN ZFA25000002S96215

Body Style Dropside LWB

MOT Due Expired

CAP Clean £6,225.00

CAP Average £5,575.00

CAP Below £4,575.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH TOW BAR, E/MIRRORS, AD BLUE.

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos






Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm

2: Seat Base Cover osf
Torn
Over 3mm



3: Sill os
Rusted
Over 5mm

4: Bonnet
Dented
Over 2 UpTo 10mm



5: Bumper Front Moulding
Broken
Replace

6: Wing osf
Dented
With Paint Damage



7: Door Mirror Assy osf
Broken
Replace

8: Door Mirror Glass os
Missing
Replace



9: Qtr Panel osr
Rusted
Over 5mm

10: Tailgate
Rusted
Over 5mm



11: Qtr Panel nsr
Dented
With Paint Damage

12: Door nsf
Dented
Over 30mm



13: Sill ns
Rusted
Over 5mm

14: Door Mirror Assy nsf
Broken
Replace



15: Door Mirror Glass ns
Missing
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK