

VEHICLE INSPECTION REPORT

MJ67YMH

Daf CF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 05/02/2018

VIN XLRAEM3700G165931

Gearbox MANUAL

Year 2018

Body Style Flatbed

Axle Combi 4x2

Mileage 522,222 Km Warranted

Service history Yes

Rear Suspension Air

Fuel Type Diesel

MOT Due 31/03/2026

Colour RED

Cab Type SLEEPER CAB

AD-BLUE, SCHEDULE LIST AVAILABLE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Not Thru Paint

2: Wing osf
Cracked
Replace



3: Fog Lamp Surround os
Scratched (Painted)
Over 25mm Thru Paint



4: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint




5: Bonnet
Chipped
Multiple Chips




6: Wing nsf
Chipped
Multiple Chips



7: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint



8: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint





9: Other
N/A
N/A

10: Door Mirror Assy nsf
Broken
Replace



11: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

12: Other
N/A
N/A



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

14: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	