COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

NG72RFF

Mercedes-Benz Sprinter 315 CDI PREMIUM

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	54799
Cap Code	MESP2031PRVDTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£15,000.00
Reg. date	17/02/2023	**Colour**	WHITE	**CAP Average**	£13,900.00
Year	2023	**VIN**	W1V9106332P526347	**CAP Below**	£12,000.00
Mileage	90,900 Miles Not Warranted	**Body Style**	Panel Van L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	05/03/2027	**Gears**	6

WARNING LIGHT ON DASH AD BLUE, SIDE LOADING DOOR

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Rear parking sensor
- Front electric windows

Photos











Mercedes-Benz
MERCEDES-BENZ AG
e1*2007/46*1760
W1V9106332P526347
3500 kg
5500 kg
1850 kg
2100 kg
1-
2-
0,50
iHA--
1,0 %
Typ: KL3A4
Made in Germany
A 907 584 32 05










Condition Check



Damage Photos



1: Number Plate Front
Broken
Replace



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing nsf
Dented
Over 30mm



4: Bumper Front
Insecure
Action Required



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Centre Console Front
Missing
Replace



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
Between 10mm + 30mm




10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel Moulding ns
Broken
Replace



12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel nsr
Dented
Over 30mm



14: Door nsr
Dented
Between 10mm + 30mm



15: Door nsr
Scratched
Over 25mm Thru Paint



16: Door osr
Dented
Between 10mm + 30mm



17: Bumper Rear
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



20: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



21: Badgedecal Rear
Missing
Replace



22: Qtr Panel osr
Dented
With Paint Damage



23: Qtr Panel osr
Dented
With Paint Damage



24: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



25: Door osf
Scratched
UpTo 25mm Not Thru Paint



26: Seat Base Cover osf
Holed
Over 3mm



27: Door osf
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK