COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BU71FZC

Mercedes-Benz Vito 110 CDI

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	48601
Cap Code	MEVI1712PFVDTM2 6 L

Details

Location	Avonmouth	**GVW**	2800kg	**CAP Clean**	£9,625.00
Reg. date	31/10/2021	**Colour**	WHITE	**CAP Average**	£8,600.00
Year	2021	**VIN**	W1V44760323825955	**CAP Below**	£7,050.00
Mileage	57,469 Miles Warranted	**Body Style**	Panel Van L2	**Gearbox**	MANUAL
		MOT Due	30/10/2027	**Gears**	6
Fuel Type	DIESEL				

AD BLUE, TWIN SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos
















MERCEDES-BENZ AG
e1*2007/46*0458
Mercedes-Benz
W1V44760323825955
2800 kg
4000 kg
1- 1490 kg
2- 1490 kg



DURITE




DURITE
POWER
FAULT
LED(Green) -- INVERTER ON
LED(Red) -- INVERTER FAULT
INVERTER REMOTE
CONTROL ON / OFF SWITCH








Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Bumper Front
Chipped
Over 5mm



3: Wing nsf
Chipped
Over 5mm



4: Wing nsf
Dented
Over 30mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Bonnet
Chipped
Over 5mm



7: Wheel nsf
Corroded
Light



8: Qtr Panel nsr
Chipped
Over 5mm



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Chipped
Over 5mm



11: Bumper Rear
Cracked
Over 25mm



12: Bumper Rear
Chipped
Over 5mm



13: Tailgate
Chipped
Over 5mm



14: Wheel osr
Corroded
Light



15: Qtr Panel osr
Chipped
Over 5mm



16: Door osf
Chipped
Over 5mm



17: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



18: Wheel osf
Corroded
Light



19: Wing osf
Chipped
Over 5mm



20: A Post os
Scratched
Over 25mm Not Thru Paint



21: Bumper Front
Chipped
Over 5mm



22: Bonnet
Chipped
Over 5mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK