COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

V555JWT

Mercedes-Benz Tourismo

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**GVW**	19000kg	**MOT Due**	25/01/2027
Reg. date	19/06/2015	**Colour**	SILVER	**Cab Type**	CREW CAB
Year	2015	**VIN**	WEB63241523000505	**Gearbox**	AUTOMATIC
Mileage	586,912 Km Not Warranted	**Body Style**	Coach	**Axle Combi**	4x2
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

5% BUYERS FEE *SMOKING HEAVILY, ENGINE NOISE, WARNING LIGHTS ON DASH* 46 SEATS + DRIVER + CREW, FABRIC RECLINING SEATS WITH FOOTRESTS & TRAY TABLES, 3 PT. SEATBELTS, CONTINENTAL SIDE DOOR, TOILET, OVERHEAD STOWAGE, SURROUND CAMERA SYSTEM, WHEELCHAIR LIFT, UNDERBODY STORAGE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Cruise control
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim
- Front electric windows

Photos










VDO
586912.5km

1 2 3 D N R

EVOBUS GMBH
EVOBUS GMBH



TOILET



PLS Mega LIFT

PLS Mega LIFT













Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Wing nsf
Scratched
UpTo 25mm Thru Paint



3: Wing nsf
Rusted
Over 5mm



4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Chipped
Over 5mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Tailgate
Chipped
Over 5mm



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Tailgate
Chipped
Multiple Chips



12: Qtr Panel osr
Chipped
Over 5mm




13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Rusted
UpTo 5mm



17: Qtr Panel osr
Rusted
Over 5mm



18: Qtr Panel osr
Dented
With Paint Damage



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Wing osf
Cracked
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	-
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	Fault
Brakes	OK		
Turbo Boosting	OK		
Parking Brake	OK		

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows	OK	Radio	OK
		Steering	OK