COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LK23CYY

FORD / SWIFT VOYAGER 594 2.0 ECOBLUE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	03/05/2023	**GVW**	3500kg	**MOT Due**	14/06/2027
Year	2023	**Colour**	GREY/WHITE	**Gearbox**	MANUAL
Mileage	35,028 Miles Not Warranted	**VIN**	WF0DXXTTRDNA03912		

4 BERTH, AD BLUE, E/MIRRORS, 2 SEAT WITH 3PT. SEATBELTS, SINK, OVEN, 4 RING GAS HOB, FRIDGE, TOILET, SHOWER, DOUBLE BED, REAR STORAGE

Tyres


NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Park assist camera
- Manual sunroof
- Passenger airbag
- Cruise control
- Rear parking sensor
- Air conditioning
- Central locking
- Front parking sensor
- Digital radio
- Front electric windows
- Cloth seat trim
- Navigation system
- USB/iPod interface
- Drivers airbag

Photos








Ford
AIRBAG

SWIFT
UK
LK23 CYY

R 1 3 5
2 4 6

TRANSIT
CAMPER
2.0 I4PCR Panther Diesel
155 PS Stage 6 HD
350EL
N0HA
FORD
e1*2007/46*1098
WF0DXXTTRDNA03912
3550
6000
1850
2250
W(mm)
L(mm)
H(mm)
L 4349
FDD




















truma

TV
12V
6A













TABLE CONTROL
WARNING: Ensure table is clear of obstructions before operation






THETFORD




truma
SDC12
MPPT
VISION PLUS
Digital TV Amplifier VP2



VISION PLUS
Digital TV Amplifier VP2
12-24VDC
TV2
TV1
ANT IN




VISION PLUS
Digital TV Amplifier VP2



DOMETIC
AUTO



















XZENT
HOME
NAV
CAM
VOICE
DAB
FAV





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Qtr Panel Moulding ns
Broken
Replace



5: Bumper Rear
Cracked
Over 25mm



6: Qtr Panel Trim ns
Broken
Replace



7: Panel Rear
Cracked
Replace



8: Qtr Panel osr
Cracked
Replace



9: Door osf
Scratched
Over 25mm Thru Paint



10: B Post ns
Scratched
UpTo 25mm Thru Paint



11: Fascia Trim
Missing
Replace



12: Fascia Trim
Missing
Replace



13: Air Vents nsf
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		