COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HJ25JUO

FORD / ROLLER TEAM AUTO ROLLER 747 2.0 ECOBLUE TURBO

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	03/04/2025	**GVW**	3500kg	**MOT Due**	02/04/2028
Year	2025	**Colour**	SILVER/WHITE	**Gearbox**	MANUAL
Mileage	25,566 Miles Not Warranted	**VIN**	WF0DXXTTRDRR78626		

CRACKED WINDSCREEN 6 BERTH, AD BLUE, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN, 6 SEATS WITH 3PT. SEATBELTS, OVERHEAD BED, DOUBLE BED, TOILET, SHOWER, SINK, OVEN, 3 RING GAS HOB, FRIDGE, FREEZER, REAR STORAGE, BIKE RACK

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- USB/iPod interface
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos






Caution
The video may appear reversed


ROLLER TEAM
AUTO-ROLLER
HJ25 JUO


Ford
AIRBAG


TRANSIT
CAMPER
2.0 l HPCR Panther Diesel
170 PS Stage 6.2
350EF
BLFB
0.50
FORD
e1*2007/46*1098
WF0DXXTTRDRR78626
3550
5065
1850
2250
kg
W(mm)
J 3954
L(mm)
a(mm)
FDD














OFF














12V
SAT
TV
230V


12V
SAT







16:23
11.11.26
Temperature
Resources
18°
10°
Unlock Screen
ROLLER TEAM









VISION PLUS
Digital TV Amplifier VP2
12-24VDC
TV2
TV1
ANT IN



PWM Solar Charge Controller




RCCB
MCB1
MCB2




















R 1 3 5
2 4 6





Condition Check



Damage Photos



1: Screen Front
Cracked
Replace




2: Bonnet
Chipped
Multiple Chips



3: A Post os
Scratched
Over 25mm Not Thru Paint



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel Moulding ns
Missing
Replace



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear Moulding
Broken
Replace



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Door osf
Scratched
Over 25mm Thru Paint



11: Door Moulding osf
Scratched (Painted)
UpTo 25mm Thru Paint



12: Fascia Trim
Missing
Replace



13: Fascia Trim
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		