COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO71LLK

Fiat Ducato Maxi 35 2.2 MULTIJET 140PS

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	52410
Cap Code	FIDU223MX4HDTM2 5 L

Details

Location	Avonmouth	**GVW**	3500kg	**CAP Clean**	£7,875.00
Reg. date	26/11/2021	**Colour**	WHITE	**CAP Average**	£7,025.00
Year	2021	**VIN**	ZFA25000002T73209	**CAP Below**	£5,750.00
Mileage	54,957 Miles Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	Diesel	**MOT Due**	Expired	**Gears**	6

NON-RUNNER-TURNS OVER DOES NOT START, PISTONS SEIZED, AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- USB/iPod interface
- Central locking
- Air conditioning
- Cloth seat trim

Photos















FIAT






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Cracked
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Chipped
Multiple Chips



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Qtr Panel nsr
Poor Previous Repair
Rippled Over 30%



9: Qtr Panel nsr
Poor Previous Repair
Rippled Over 30%



10: Sill ns
Dented
Hail - Severe



11: Qtr Panel nsr
Dented
Hail - Moderate



12: Qtr Panel nsr
Chipped
1 To 5



13: D Post ns
Dented
With Paint Damage



14: Tailgate
Dented
Hail - Moderate



15: Bumper Rear
Cracked
Over 25mm



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Dented
Between 10mm + 30mm



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Door osf
Chipped
Multiple Chips



21: Door Mirror Assy osf
Broken
Replace



22: Wing osf
Scratched
Over 25mm Thru Paint



23: Bumper Front
Cracked
Over 25mm



24: Carpets Front
Holed
Over 3mm



25: Centre Console Front
Holed
UpTo 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-
Engine Runs	Fault		

Commercial Vehicle Auctions Limited