



Commercial Vehicle Auctions Ltd.

LM66MKE

CN: WF0XXXTTGXGL51465

Photos



General Details

FORD TRANSIT 350 2.0 TDCI 130PS

Vat Status: Commercial (plus Vat)

Mileage	159,333 miles	Miles Warranty	
Colour	Green	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	07/12/2016	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2016	Yes



Valid MOT
Expires: 06/12/2025



V5 with CVA

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm


Interior Condition

Carpets	Poor
Upholstery	Good
Seats	Good
Odour	Good
Comments	

Service History

Service	No
History	
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Roof	Chipped	Multiple Chips	Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel Trim ns	Broken	Replace	Replace
Door nsr	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Seat Base Cover osf	Torn	Over 3mm	Replace
Carpets Front	Torn	Over 10mm	Replace
Screen Front	Chipped	Over 10mm	Replace

Vehicle Splat



Splat Key

- S3**
Scratch/Paint defect 100m +
- D3**
Dent/damage 100mm +
- C2**
Multiple Chips
- K**
Crack/Torn

Damage Assessment




Bonnet

Chipped
Multiple
Chips
Refinish



Roof

Chipped
Multiple
Chips
Refinish




Wing nsf

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Qtr Panel nsr

Scratched
Over
25mm
Thru Paint
Refinish



Qtr Panel nsr

Dented
Over
30mm
Repair
and
Refinish



Qtr Panel nsr

Dented
Over
30mm
Repair
and
Refinish




Qtr Panel nsr

Scratched
Over
25mm
Thru Paint
Refinish




Qtr Panel Trim ns

Broken
Needs
Replaced
Replace



Door nsr

Scratched
Over
25mm
Thru Paint
Refinish



Door osr

Scratched
Over
25mm
Thru Paint
Refinish




Door osr

Dented
Over
30mm
Repair
and
Refinish



Door osr

Dented
Over
30mm
Repair
and
Refinish



Qtr Panel osr

Dented
Over
30mm
Repair
and
Refinish




Qtr Panel osr

Dented
Over
30mm
Repair
and
Refinish




Qtr Panel osr

Dented
Over
30mm
Repair
and
Refinish



Door osf

Scratched
Over
25mm
Thru Paint
Refinish



Seat Base Cover osf

Torn
Over 3mm
Replace



Carpets Front

Torn
Over
10mm
Replace



Screen Front



Chipped
Over
10mm
Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.