COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

VEHICLE INSPECTION REPORT

CU14BYW

Ford Transit T350 2.2 TDCI 125PS

Non Runner

Inspection

		Vehicle	
Serious Damage?	No	**VAT**	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	01/03/2014	**VIN**	WF0XXXTTFXDD14605	**CAP Below**	£1,200.00
Year	2014	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Mileage	91,495 Miles Warranted	**MOT Due**	Expired	**Gears**	6
Fuel Type	Diesel	**CAP Clean**	£2,200.00		
Colour	WHITE	**CAP Average**	£1,725.00		

NON RUNNER - TURNS OVER, DOES NOT START - TURBO FAULT, ENGINE USING OIL, NO REAR ACCESS HEATED WINDSCREEN, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag

Photos

Condition Check

Damage Photos

1: Wing osf
Dented
Over 30mm

2: Wing nsf
Dented
With Paint Damage

3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing nsf
Dented
With Paint Damage

5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Door Mirror Glass ns
Missing
Replace

7: Sill ns
Rusted
Over 5mm

8: Qtr Panel nsr
Dented
Over 30% Of Panel

9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

11: C Post ns
Dented
With Paint Damage

12: Door nsr
Dented
Over 30mm

13: C Post os
Dented
With Paint Damage

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint

15: Qtr Panel osr
Scratched
Over 25mm Thru Paint

16: Sill os
Rusted
Over 5mm

17: B Post os
Rusted
Over 5mm

18: Door osf
Dented
With Paint Damage

19: Carpets Front
Holed
Over 3mm

20: Fascia Panel
Missing
Replace

Commercial Vehicle Auctions Limited

21: Seat Base Cover osf
Holed
Over 3mm

22: Seat Base Cover nsf
Soiled
Heavy

23: Seat Back Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No
Engine Runs		Fault	