Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WX17USV

Isuzu D-Max 2.5 TD

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply

Details

Reg. date	01/03/2017	**VIN**	MPATFS86JFT031369	**CAP Below**	£2,825.00
Year	2017	**Body Style**	Pickup Double Cab	**Gearbox**	MANUAL
Mileage	139,174 Miles Warranted	**MOT Due**	Expired	**Gears**	6
Fuel Type	Diesel	**CAP Clean**	£4,525.00	**Axle Combi**	4x4
Colour	WHITE	**CAP Average**	£3,850.00		

WARNING LIGHTS ON DASH TWIN SIDE LOAD DOOR, REMOTE WINCH, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Air conditioning
- Front electric windows
- Central locking

Photos





WX17 USV

WINCH IN



DANGER
240 VOLTS
ANTARES

Condition Check



Damage Photos

1: Carpets Front
Holed
Over 3mm

2: Seat Base Cover osf
Holed
Over 3mm

3: Dash Warning Lights
Displayed
No Action

4: Screen Front
Cracked
Replace

5: Bonnet
Chipped
Multiple Chips

6: Bumper Front
Hole
UpTo 25mm

7: A Post ns
Rusted
Over 5mm

8: Door nsf
Scratched
Over 25mm Thru Paint

9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel nsr
Dented
With Paint Damage

11: Panel Rear
Scratched
Over 25mm Thru Paint

12: Door nsr
Cracked
Replace

13: Lamp osr
Broken
Replace

14: Bumper Rear
Insecure
Action Required

15: Qtr Panel osr
Chipped
Multiple Chips

16: Qtr Panel osr
Chipped
Multiple Chips

17: Door osf
Scratched
Over 25mm Thru Paint

18: Aerial
Missing
Replace

19: Roof
Rusted
Over 5mm

20: Wing osf
Rusted
Over 5mm

21: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



22: Sill os
Rusted
Over 5mm

23: Sill ns
Scratched
Over 25mm Thru Paint

24: Wing Front Arch Extension ns
Broken
Replace

Interior

Carpet Condition	Poor	**Upholstery Condition**	Average
Seat Condition	Poor	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Steering	OK