COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KF24BWZ

Peugeot Partner 1.5 BLUEHDI 100PS PROFESSIONAL

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	58102
Cap Code	PEPA15S1P0VDTM2 6 L

Details

Location	Livingston	**GVW**	2370kg	**CAP Clean**	£8,775.00
Reg. date	31/08/2024	**Colour**	WHITE	**CAP Average**	£8,300.00
Year	2024	**VIN**	VR3EDYHT7RJ833985	**CAP Below**	£7,275.00
Mileage	59,367 Miles Not Warranted	**Body Style**	Panel Van SWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	30/08/2027	**Gears**	6

COLLECTED AS NON RUNNER - WARNING LIGHT ON DASH, INTERMITTENT LIMP MODE SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Rear parking sensor
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking

Photos



















0
mph
59367 mi


STELLANTIS AUTO SAS
VR3EDYHTTRJ833985
2390 KG
3390 KG
1 – 1200 KG
2 – 1400 KG





AIRBAG












Condition Check



Damage Photos



1: Bumper Front
Insecure
Action Required



2: Door osr
Dented
With Paint Damage



3: Bumper Rear
Cracked
Over 25mm



4: Carpets Front
Holed
Over 3mm



5: Seat Base Cover nsf
Soiled
Heavy



6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault