COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CE74YDA

Vauxhall Vivaro F2900 1.5 TURBO D 120PS PRIME

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	58180
Cap Code	VAVI15L2P VDTM2 4 L

Details

Location	Doncaster	**GVW**	2830kg	**CAP Average**	£12,100.00
Reg. date	01/09/2024	**Colour**	WHITE	**CAP Below**	£10,650.00
Year	2024	**VIN**	VXEVJYHV1R7833814	**Gearbox**	MANUAL
Mileage	35,249 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gears**	6
Fuel Type	DIESEL	**CAP Clean**	£12,850.00		

WARNING LIGHTS ON DASH, N/S SIDE DOOR HANDLE MISSING AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

Photos










0
mph
35249 mi


AUTOMOBILES PEUGEOT
VXEVJYHV1R7833814









AIRBAG







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Panel Front
Scratched
Over 25mm Thru Paint



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Wing nsf
Dented
Over 30mm



7: Sill ns
Dented
Over 30mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Sill ns
Dented
With Paint Damage



13: Qtr Panel nsr
Dented
With Paint Damage



14: Door nsr
Dented
With Paint Damage



15: Bumper Rear
Cracked
Over 25mm



16: Door osr
Dented
Over 30mm



17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



19: Qtr Panel osr
Dented
With Paint Damage



20: Qtr Panel osr
Dented
With Paint Damage



21: Qtr Panel osr
Dented
With Paint Damage



22: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



23: Qtr Panel osr
Scratched
Over 25mm Thru Paint



24: Qtr Panel osr
Dented
With Paint Damage



25: Door osf
Scratched
Over 25mm Thru Paint



26: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



27: Handle Outer nsr
Missing
Replace



28: Seat Base Cover osf
Holed
Over 3mm



29: Dash Warning Lights
Displayed
No Action



30: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK