COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CE74YDG

Vauxhall Vivaro F2900 1.5D 100PS PRIME

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	58180
Cap Code	VAVI15L2P VDTM2 4 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£11,900.00
Reg. date	01/09/2024	**VIN**	VXEVJYHV0R7833819	**CAP Below**	£10,500.00
Year	2024	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Mileage	38,436 Miles Not Warranted	**Service history**	None	**Gears**	6
Fuel Type	DIESEL	**MOT Due**	31/08/2027		
GVW	2830kg	**CAP Clean**	£12,650.00		

OUTSTANDING RECALL TWIN SIDE LOAD DOORS, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos

























Commercial Vehicle Auctions Limited


AIRBAG






Condition Check




Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Bumper Front
Dented
Over 30mm



3: Panel Front
Dented
With Paint Damage



4: Bumper Front
Cracked
Over 25mm



5: Door nsf
Dented
With Paint Damage



6: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



7: Sill ns
Dented
Over 30% Of Panel



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel Moulding ns
Missing
Replace



10: Qtr Panel nsr
Dented
Over 30% Of Panel



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



12: Door nsr
Dented
With Paint Damage



13: Door nsr
Dented
With Paint Damage



14: Door osr
Dented
With Paint Damage



15: Door osr
Dented
With Paint Damage



16: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel osr
Dented
With Paint Damage



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Sill os
Dented
Over 30% Of Panel



21: Qtr Panel osr
Scratched
Over 25mm Thru Paint



22: Door osf
Dented
With Paint Damage



23: Door Moulding osf
Missing
Replace



24: Seat Base Cover osf
Holed
Over 3mm



25: Seat Base Cover nsf
Soiled
Heavy



26: Dash Warning Lights
Displayed
No Action



27: Air Vents osf
Missing
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault