COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CE74YDN

Vauxhall Vivaro XL F2900 1.5 TURBO D 120PS PRIME

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	58180
Cap Code	VAVI15L2P VDTM2 4 L

Details

Location	Doncaster	**GVW**	2830kg	**CAP Average**	£12,450.00
Reg. date	03/09/2024	**Colour**	WHITE	**CAP Below**	£10,950.00
Year	2024	**VIN**	VXEVJYHV3R7833832	**Gearbox**	MANUAL
Mileage	29,444 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gears**	6
Fuel Type	DIESEL	**CAP Clean**	£13,200.00		

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag



Photos













0
mph
29444 mi


AUTOMOBILES PEUGEOT
VXEVJYHV3R7833832











AIRBAG







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Panel Front
Cracked
Replace



4: Headlamp ns
Broken
Replace



5: Panel Front
Scratched
Over 25mm Thru Paint



6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Wing nsf
Dented
With Paint Damage



8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Wing nsf
Dented
Over 30mm



10: Sill ns
Dented
Over 30% Of Panel



11: Door nsf
Scratched
Over 25mm Thru Paint



12: Door Moulding nsf
Missing
Replace



13: Qtr Panel nsr
Dented
With Paint Damage



14: Qtr Panel Moulding ns
Missing
Replace



15: Qtr Panel nsr
Dented
With Paint Damage



16: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



17: Door nsr
Dented
Over 30mm



18: Door osr
Dented
Over 30% Of Panel



19: Bumper Rear Moulding
Broken
Replace



20: Qtr Panel osr
Dented
With Paint Damage



21: Qtr Panel osr
Scratched
Over 25mm Thru Paint



22: Seat Base Cover osf
Holed
Over 3mm



23: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK