COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CF24UCJ

Vauxhall Vivaro F2900 1.5D 120PS Prime

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	58180
Cap Code	VAVI15L2P VDTM2 4 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£11,850.00
Reg. date	31/07/2024	**VIN**	VXEVJYHV8R7833888	**CAP Below**	£10,450.00
Year	2024	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Mileage	33,590 Miles Not Warranted	**Service history**	None	**Gears**	6
Fuel Type	DIESEL	**MOT Due**	30/07/2027		
GVW	2830kg	**CAP Clean**	£12,550.00		

TWIN SIDE LOAD DOORS, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

Photos










0
mph
KISSTORU
DAB
33590 mi


















Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Dented
Over 30mm



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Sill ns
Dented
With Paint Damage



6: Door nsf
Dented
Over 30% Of Panel



7: Door Moulding nsf
Missing
Replace



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage



12: Qtr Panel nsr
Dented
With Paint Damage



13: Door nsr
Dented
With Paint Damage



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osr
Dented
Over 30mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



18: Qtr Panel osr
Dented
Over 30mm



19: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



20: Door osf
Dented
With Paint Damage



21: Door Moulding osf
Missing
Replace



22: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



23: Seat Base Cover osf
Holed
Over 3mm



24: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK