COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DN23VTL

Vauxhall Vivaro 2900 1.5d 100PS Prime H1

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	56184
Cap Code	VAVI1529P1VDTM2 3 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£7,975.00
Reg. date	30/04/2023	**VIN**	VXEVBYHRMP7814965	**CAP Below**	£6,850.00
Year	2023	**Body Style**	Panel Van L2	**Gearbox**	MANUAL
Mileage	59,648 Miles Not Warranted	**Service history**	None	**Gears**	6
Fuel Type	DIESEL	**MOT Due**	06/05/2027		
GVW	2830kg	**CAP Clean**	£8,600.00		

WARNING LIGHT ON DASH TWIN SIDE LOAD DOORS, AD-BLUE, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

Photos










0
37 MI
059648 MI




0
mph
37 MI
059648 MI
SET 000


AUTOMOBILES PEUGEOT
VXEVBYHRMP7814965


















Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Dented
With Paint Damage



6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Dented
With Paint Damage



8: Sill ns
Dented
Over 30% Of Panel



9: Door Moulding nsf
Missing
Replace



10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel Moulding ns
Missing
Replace



12: Qtr Panel nsr
Dented
With Paint Damage



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Qtr Panel nsr
Dented
With Paint Damage



15: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel nsr
Dented
With Paint Damage



18: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



19: Bumper Rear
Dented
Over 30mm



20: Door nsr
Dented
With Paint Damage



21: Door osr
Dented
With Paint Damage



22: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm




23: Qtr Panel osr
Dented
With Paint Damage



24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Qtr Panel osr
Dented
With Paint Damage



26: Qtr Panel osr
Scratched
Over 25mm Thru Paint



27: Qtr Panel Moulding os
Missing
Replace




28: Sill os
Dented
With Paint Damage



29: Door osf
Dented
With Paint Damage



30: Door Moulding osf
Missing
Replace



31: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



32: Seat Base Cover nsf
Soiled
Heavy



33: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault