COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MM23LLV

Ford Transit Custom 300 2.0 EcoBlue 130ps TREND

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	42076
Cap Code	FOTU20LT33HDTM2 1 L

Details

Location	Doncaster	**GVW**	3000kg	**CAP Clean**	£9,425.00
Reg. date	23/05/2023	**Colour**	WHITE	**CAP Average**	£8,750.00
Year	2023	**VIN**	WF0YXXTTGYNR64878	**CAP Below**	£7,500.00
Mileage	85,516 Miles Not Warranted	**Body Style**	Panel Van L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	08/07/2027	**Gears**	6

WARNING LIGHTS ON DASH, OUTSTANDING RECALL SIDE LOAD DOOR, E/MIRRROS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Central locking
- Front parking sensor
- Air conditioning
- Cloth seat trim
- Rear parking sensor
- Front electric windows

Photos










Speedometer
0 mph
855 16.6 mls


FORD














Condition Check



Damage Photos



1: Door nsf
Scratched
Over 25mm Thru Paint



2: Door nsf
Dented
With Paint Damage



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Door Moulding nsf
Missing
Replace



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
Over 30mm



10: Door osr
Dented
With Paint Damage



11: Door osf
Dented
Over 30mm



12: Door osf
Dented
With Paint Damage



13: Door osf
Dented
Over 30mm



14: Seat Base Cover osf
Holed
Over 3mm



15: Seat Base Cover nsf
Soiled
Heavy



16: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK