COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CJ71EUP

Citroen Berlingo 1.5 BlueHDi Enterprise Pro 100ps

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	53412
Cap Code	CIBE15EPR6VDTM2 4 L

Details

Location	Doncaster	**GVW**	2370kg	**CAP Clean**	£4,875.00
Reg. date	31/01/2022	**Colour**	WHITE	**CAP Average**	£4,425.00
Year	2022	**VIN**	VR7EFYHT2MJ960781	**CAP Below**	£3,725.00
Mileage	94,132 Miles Not Warranted	**Body Style**	Panel Van SWB	**Gearbox**	MANUAL
		MOT Due	30/01/2027	**Gears**	6
Fuel Type	DIESEL				

WARNING LIGHTS ON DASH, OUTSTANDING RECALL SIDE LOAD DOOR, AD-BLUE.

Tyres




NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking

Photos







PSA AUTOMOBILES SA
VR7EFYHT2MJ960781
2390 KG
3690 KG
1 – 1200 KG
2 – 1400 KG





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front
Rusted
Over 5mm



4: Qtr Panel osr
Chipped
1 To 5



5: Qtr Panel osr
Dented
Over 30mm



6: Door nsf
Chipped
Multiple Chips



7: Wing nsf
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault